Flight Scientist Report
Thursday 06/02/2022 ACTIVATE RF162

Flight Type: Statistical Survey Flight

Flight Route:

Special Notes: Doing a spiral by the Tudor Hill site at end of flight w/ Falcon. UC12 experienced

maintenance issue prior to takeoff and did not fly.

King Air

Pilot report ():

Flight scientist report ():

Falcon

Pilot report (Baxley):

Planned ACTIVATE mission with HU-25 and UC-12 coordinated flight, flown by HU-25 only. Initial plan TXKF-FOXIT-PERDO-FOXIT-Tudor Hill-TXKF, however deviated significantly at the direction of the research team.

Flight scientist report ():


Winstead:


11:23:15 Wet neph <100% RH after being high since startup.


11:30 Lower humidifier by 1- degree. Controlling RH difficult


12:59:15 Spiral up

13:58:40 Spiral up near Bermuda coast at 500 ft/min











Only pure liquid clouds with Precip.









Cloud Droplet Number Concentration (cm-3)

